Steering: All Technical Service Bulletins Steering/Suspension - Idler Arm Grease Fitting Bulletin No.: 03-00-90-001B

Date: January 20, 2006

INFORMATION

Subject: Recommended Idler Arm Grease Fitting Due to Limited Access

Models: 2003-2006 HUMMER H2

Supercede:

This bulletin is being revised to add model years. Please discard Corporate Bulletin Number 03-00-90-001A (Section 00 - General Information).

The idler arm on the HUMMER H2 has a grease fitting near the top end of the shaft facing the right-hand frame rail. Access to this fitting is very limited and may be accomplished, although not easily, with the use of a 90° grease gun adapter. However, to assure an adequate lubrication at each maintenance interval, it is recommended that the grease fitting be replaced with a 9°0 style fitting, P/N 09417903, pointing upward.

| Part Number | Description |
|----------------|--------------------|
| 09417903 | 90° Grease Fitting |

Parts Information

Warranty Information

| Labor Operation | Description | Labor Time | |
|--------------------|------------------------------|---------------|--|
| E7939 | Fitting, Grease – Replace | 0.3 hr | |

For vehicles repaired under warranty, use the table.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the property service of a vehicle. Properly trained technicians have the equipment, tools, salety instructions, and know-how to do a job properly and salely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

Disclaimer